
Kramer Apartments Corporation Kramer Service Corporation


District 8, SR 58 San Bernardino County


Michael Whiteside Assistant Chief Engineer Caltrans



Project Location っ Bishop SU **Kramer Apartments Corp.** To Bakersfield 395 ROUTE 58 **Kramer Service Corp. BNSF Grade** Separation 20 Mule Team Road **Edwards Air Force Base Boundary** Exist Route 58 KERN COUNTY BERNARDINO COUNTY Route 58/395 Separation **Edwards Air Force** To San Bernardino Base To Barstow SAN

Project Location






Contacts


Mail	35
Phone	30
Email	87
Personal	26

Motel Parcel (3.08 Ac)




Motel Parcel






Antique Parcel (0.75Ac)



Antique Parcel





Related to the findings of the Commission:

This project is planned and located in a manner that will be most compatible with the greatest public good and least private injury.


THE PROPERTY OWNER CONTENDS:

Property lines incorrect on drawings

Buildings don't traverse property lines

Parking access not to code in after condition Northern driveway a raised median

Access commercial / over-sized vehicles



Related to the findings of the Commission:

This project is planned and located in a manner that will be most compatible with the greatest public good and least private injury.

THE PROPERTY OWNER CONTENDS:

Property lines incorrect on drawings

Buildings don't traverse property lines

DEPARTMENT RESPONSE:

Confirmed - Buildings traverse property lines Acquisition doesn't impact building

Related to the findings of the Commission:

This project is planned and located in a manner that will be most compatible with the greatest public good and least private injury.

THE PROPERTY OWNER CONTENDS:

Parking access not to code in after condition

DEPARTMENT RESPONSE:

San Bernardino code 51' setback Final 63' provided

Related to the findings of the Commission:

This project is planned and located in a manner that will be most compatible with the greatest public good and least private injury.

THE PROPERTY OWNER CONTENDS:


Northern driveway raised median

Access concerns commercial / over-sized vehicles


DEPARTMENT RESPONSE:

Median required for safety
Proximity to signalized intersection
Southern signalized driveway
Trucks can enter/exit


Antique Parcel




Service Parcel (16.88 Ac)





Existing Utility Corridors
















Related to the findings of the Commission:

This project is planned and located in a manner that will be most compatible with the greatest public good and least private injury.

THE PROPERTY OWNER CONTENDS:

Replacement private utilities

Design is incorrect

DEPARTMENT RESPONSE

Meeting June 23

Sizes agreed upon

Steel casings - 2 water, 1 sewer, 1 future

Resolved

Related to the findings of the Commission:

This project is planned and located in a manner that will be most compatible with the greatest public good and least private injury.

THE PROPERTY OWNER CONTENDS:

Left u-turns be allowed at Salton Rd

DEPARTMENT RESPONSE

No u-turn restrictions at Salton Rd

Related to the findings of the Commission:

This project is planned and located in a manner that will be most compatible with the greatest public good and least private injury.

THE PROPERTY OWNER CONTENDS:

Northern remainder

Move SCE pole to CT R/W

DEPARTMENT RESPONSE

SCE designed relocation

Within in existing easement

Line spans limited & balanced

Safety & access

Relocated to minimize impact

Limitations compensation issue

Related to the findings of the Commission:

This project is planned and located in a manner that will be most compatible with the greatest public good and least private injury.

THE PROPERTY OWNER CONTENDS:

Replace poles w/ tubular steel

No guy wires

Shorten guy wires

Meeting with SCE and CT

DEPARTMENT RESPONSE

SCE designed

Within existing easement

SCE - tubular steel not feasible / clearance

Many SCE meetings – design/redesign complete

Will attend meeting

Impacts compensation issue

Related to the findings of the Commission:

This project is planned and located in a manner that will be most compatible with the greatest public good and least private injury.

THE PROPERTY OWNER CONTENDS:

CT is seeking new rights for SCE

Existing has no provision for underground

Terms of SCE underground easement not reasonable

Should be negotiated

DEPARTMENT RESPONSE:

Yes, seeking underground easements
SCE requirements / issued easement language
Not stated specific objections
Impacts compensation issue

All Parcels

Related to the findings of the Commission:

That a valid offer of compensation has been made.

THE PROPERTY OWNER CONTENDS:

Valid offer not made

- Private air strip
- NextEra easement extinguished

DEPARTMENT RESPONSE

Written offers made


- Service Parcel March 2016 / rev. Jan 2017
- Antique Parcel March 2016 / rev Jan 2017
- Motel Parcel March 2016

Included airstrip, easements, & encumbrances


Summary

- 1. The public interest and necessity require the proposed project.
- 2. This project is planned and located in a manner that will be most compatible with the greatest public good and least private injury.
- 3. The property sought to be condemned is necessary for the proposed project.
- 4. An offer of compensation has been made.

Northerly Remainder Service Parcel








Existing Utility Corridors



Existing Utility Corridors





SCE Transmission Relocation Letter



Chad Packard Estimator Northwest Transmission

March 24, 2017

Tanisha Barfield Caltrans District 8 Right of Way Division 464 W 4th St San Bernardino, CA 920401

Subject: Caltrans Highway 58 and Kramer Junction Transmission Facilities Project 1001
Work Order TD1012131

Southern California Edison (SCE) reviewed the design and engineering for the Highway 58 and Kramer Junction Project proposed Tubular Steel Pole 4896011E, location. In order to stay within SCE's safety, maintenance, and Design Standards the span distance would need to be limited to 488.6 feet from the northern pole 4896010E.

This was based on the conductor size and weight, tensions, span length, pole circumference, pole height, and footing size and depth.

If you have any questions, please feel free to call me at (760) 954-1924.

Sincerely,

Chad Packard Estimator


Highland Transmission

Cc; James Booth Project File Martin Barriga


Cindy Quinn

6655 Escondido Avenue Hesperia, CA 92345 Chad.Packard@SCE.com

Southerly Service, Antique and Motel Remainder Parcels



Southerly Service, Antique and Motel Remainder Parcels



Design Changes Negotiated

Interchange layout

Minimize impacts

Constructing 60' driveway and signalized intersection

Intersection directly into property

R/W reduced 25' feet avoid workshop

Setback SCE poles 25'/50'

- Clear areas
- Extra space into driveway

Ramp access control from 300' – 100'

- Future development
- Maintain access

Paved access north remainder / designated left-turn

Maintain access

Replace/encase private utilities & extra casing for future